## **Ceramic Conveyor Belt**




## **Features**

**Application:** Used in port, mine, steel industries, suitable for short distance conveyor, conveyor speed is fast, belt easy to wear, such as stacker hoist cantilever belt.

Carcass: EP, Steel Cord

## **Working Conditions:**

- Temperature of belt surface is not over 100°C
- Elevating angle of conveyor up to 15°
- Angle of roller trough up to 45°



## Construction

- a. Use the ultra-high wear resistance of ceramics.
- b. Combine the ceramic plate with the rubber surface by chemical, structural and other methods ,making it a kind of ceramic conveyor belt with ultra-high wear resistance.
- c. The wear-resistant properties are more than 4 times that of ordinary wear-resistant conveyor belts.